

City of Detroit
Department of Recreation Performance Audit
Exhibit 3 – River Rouge Park

Pool

Overall Evaluation – Good Condition

- Brennan Pool was located in the park.
- Some dirt had collected in the bottom of the pool.
- Facilities were well-maintained.




Pool appeared to be relatively well-maintained.

City of Detroit
Department of Recreation Performance Audit
Exhibit 3 – River Rouge Park



Diving boards were well-maintained.



Some dirt had collected in the bottom of the pool.